## In the Abstract, please amend as follows:

downstream-side tip thereof.

Pilot fuel being-injected from fuel injection ports 21 of a pilot nozzle 2 bumps against an inner wall surface of the atapered portion of the an inner circumference of a cone 41 of a pilot cone 4. At this time, the position where the a pilot fuel from the fuel injection ports 21 hits is located in the a range from the a middle of the tapered portion of the inner circumference of a cone 41 to the a